

CONTRACT FOR REPAIRS TO CHICKERING 9' GRAND 15392

Repair soundboard, shim cracks with solid spruce, reglue loose ribs to board.		
Strip board, sand, touch up repairs, refinish with decal.		\$300.00
Install large decal (\$150)		\$150.00
Bridge repairs:		
A. Clean, dry scrape, relubricate. Check all bridgepins for proper seating.		\$250.00
B. Recapping, hand notched, drilled and pinned.		
Bass _____ Tenor-Treble _____	\$	
C. New Bridges: Laminated, hand notched, drilled, pinned.		
Bass _____ Tenor-Treble _____	\$	
D. Repairs	\$	
New pinblock repairs: Fitting of block to plate flange. Drill plate screw holes. Install plate screws.		
Drill tuning pin holes. Fit and install block to case inner rim.		\$2,500.00
Restringing repairs: New steel music wire. Bass strings copper wound. Wire coils handmade.		
New tuning pins 2/0 x 2 1/2 (.281). Level and space strings. Chip tune 4 times.		
Finished tune before delivery. One tuning and check up after delivery.		\$2,500.00
Plate repairs: Primer coat, regilding of plate, two coats of black, two coats clear top finish.		
Hand lettered. Refloat plate. Set bearing. Screw down plate. Tighten and set all bolts, decal.		\$750.00
Agraffe repair: New Bass _____, New Tenor _____ Installed, leveled	\$	
Action Rebuilding:		
A. New Hammers, set of 88 (wool), installed Renner Premium Blue with shanks.		\$1,500.00
B. Reshape hammers	\$	
C. New hammer shank rest felts, installed	\$	
D. Back checks, recovered	\$	
New back checks, installed	\$	
E. New key tops (naturals)		\$350.00
F. New key fronts	\$	
G. New black tops		\$150.00
H. Rebush keys. Balance rail ___X___ Front rail ___X___		\$250.00
I. Balance rail pins (new) installed (Keyframe)	\$	
J. Repair balance rail holes in keys (New wood)	\$	

K. New key sides (Wood)	\$	
L. Refelting: Front rail punchings, Balance rail punchings, Back rail cloth	\$	
M. Regulation of action includes: Key level, key depth, hammers spaced to strings, hammer blow distance, let-off drop, back check distance, repetition springs reset		\$650.00
N. New repetitions installed	\$	
O. Repetitions reconditioned		\$350.00
P. Voicing and tone regulation, fit hammers to strings.		\$600.00
Q. Tighten all screws, realign parts	\$INC	
R. Lubricate all friction points	\$INC	
S. Clean, light sand, and buff ivories		
T. Hand polish all key pins.		\$150.00
U. Other	\$	
Dampen repairs: Refelt damper heads. Install and regulate.		\$500.00
Damper underlevers: New set installed _____ Reconditioned _____ Regulated _____	\$	
Repair Music Desk	\$	
Trapwork repairs, install new pedals		\$350.00
Refinishing-Final cost after finish removed		
A. Standard Procedure: Remove all old finish, including filler. Dry and sand. Stain coat, silex filler, two coats sanding sealer. Dry and sand. Two coats lacquer. Clean and buff all metal parts. Finish in original color.	\$	
B. Premium Procedure: Remove all old finish, including filler. Dry and sand. Stain coat, silex filler, two coats sanding sealer. Dry and sand. Six coats lacquer, sand level. Top coats lacquer as needed, finish to desired sheen. Clean and buff all metal parts.		\$6,000.00
Case repairs: Touch up and polish, clean inside of piano.	\$	
Bench: Refinish _____ New Concert Adjustable Bench, Naugahyde, Black		\$600.00
Reglue leg joints and reinforce on all three legs.		
Install 3 new solid brass castors, double wheel		\$450.00
Install QRS Ancho record and playback system, calibrate and test.		\$8,500.00

Install 5 part environmental control system		\$600.00
Cartage to residence, pickup already paid.	\$	
Sub-total		\$27,450.00
PA Sales Tax 6%	\$	
Total - Good until	\$	
Deposit	\$	
Deposit	\$	
Balance	\$	

Approved/Owner \_\_\_\_\_

Approved Technician \_\_\_\_\_

Robert W. Wagner POB 183, Champion PA 15622 724-593-2350 info@pianotec.com